

Indiana State Board of Health
INSPECTION REPORT
Open Dumping

US EPA RECORD CENTER REGION 5



590346

Property Location Waterworks Road, County Walash 85 52
Walash, IN Date 10-23-85

Range _____ Township _____ Section _____ Site # _____

circle one

INVESTIGATION FINDINGS

- | | | |
|--|-----------------|-----------------|
| 1. Solid waste observed | Yes | |
| 2. Are flammable wastes present | Yes | |
| 3. Is access restricted | Yes | |
| 4. Is there evidence of burning on site | Yes | |
| 5. Are wastes being deposited in water
(if yes, please explain) | Yes | |
| 6. Approximate size of site | less than 1/4 A | more than 1/4 A |

Property Owner:

Name Container Corp. of America
Address Walash, IN

Inspector's Signature(s):

Chris O'Pry
Bill Baxter (County Sanitarian)

Comments/Observations This inspector received a number of complaints from R. Gill regarding Container Corporation of America dumping a paper sludge. State & County inspector drove, walked, and reviewed maps & files but could not locate any dump on Waterworks Road as alleged. Inspector D. Brown remembers vaguely a co-inspection with T. Kelly of said site but cannot recall where. Mr. Dunn ~~at site~~ stated that Spring Valley LF is receiving the said waste. This inspector will reconult with R. Gill on location & begin search again if appropriate.

Received by: see comments

Date: 10-23-85 Time: 11:00 PM

Indiana State Board of Health
INSPECTION REPORT
Open Dumping

SM A
Hm

Property location Waterworks Road, County Wabash
4 miles east of Wabash Date 11-20-85
Range _____ Township _____ Section _____ Site # 85 52

circle one

INVESTIGATION FINDINGS

1. Solid waste observed ☒ Yes ☐ No
2. Are flammable wastes present Yes ☒ No
3. Is access restricted ☒ Yes ☐ No
4. Is there evidence of burning on site Yes ☒ No
5. Are wastes being deposited in water (if yes, please explain) Yes ☒ No
6. Approximate size of site less than 1/4 A ☒ more than 1/4 A

Property Owner:

Inspector's Signature(s):

Name Unknown
Address _____

Chris Oppy

Comments/Observations Site has had extensive amounts
of paperpulp sludge dumped on-site. This material
is from United Container Corporation.
a follow up to this will occur.
Photos taken

Received by: no one on-site Date: 11-20-85 Time: 1:00 PM

Wabash

Record Number 85-1000

SM

Department of Environmental Management
INSPECTION REPORT
Open Dumping

N or S N

County Code 85

Inspector CMO

Property Location 8 mi E of Wabash

NC or IC (circle one)

Initial or Follow-up (circle one)

Inspection date 1 / 1
(mm/dd/yy)

Compliance Date 8, 12, 87
(mm/dd/yy)

INVESTIGATION FINDINGS
(circle one)

1. Solid Waste Observed: Yes No
2. Are flammable wastes present? Yes No
3. Is access restricted? Yes No
4. Is there evidence of burning on site? Yes No
5. Are Wastes being deposited in water?
(If yes, please explain) Yes No
6. Approximate size of site (circle one)
Less than 1/4 A
~~More than 1/4 A~~

Property Owner:

Name Container Corporation

Address _____

Inspector's Signature(s)

Chris Oppy

Sta Miller

Comments/Observations (Highlight for data entry)

Site was inspected as the former
disposal area of paper pulp sludge.

Inspection found no new sludge
disposed of on-site, & site is in
good enough condition to ~~not~~ merit
no further follow up.

Recorded by: NO ONE ON-SITE

Date: 8-12-87

Time 3:30 PM

Copy will be kept in DEM
file